



Sticklers® Benchtop CleanWipes™



OVERVIEW

Sticklers® CleanWipes™ 90 benchtop wipes are high quality, lint-free wipes engineered for use on bare fiber before splicing, and also for cleaning fiber optic jumpers. They are exactly the right size and the right material to make “wet-dry” cleaning simple and cost-effective.

- Optical-Grade Lint-Free Wipe, in mini-tub or Flat Wipe
- Made Without Glues, Bleach or Cellulose
- Makes “Wet-Dry” Cleaning of Fiber Optic Connectors Easy
- Far Stronger and Less Linting than Cellulose Wipes
- Superior Results When Cleaning Bare Fiber
- Very Affordable on a Cost-Per-Cleaning Basis

Part Number	Package	Weight	Size
MCC-WFW	Mini-tub		90 4in by 2in (10 cm by 5 cm) wipes